ECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 93-27538

AL CUSTOMER ORDER NO.
IN

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
/07/93	12/15/93	BN 1-66	193953		700 222 ADL

ESSORIES W/STUDS / SCOPE BASE

M: Set up file

BILLY FREDS SALES CO
PO BOX 7646
2465 I-40 WEST
AMARILLO TX 79109

SHIP TO:
BILLY FREDS SALES CO
PO BOX 7646
2465 I-40 WEST
AMARILLO TX 79109

CUST NO:006802 WILM

OUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				1-14-94	UPS

CONDITION
NEW
LIGHTLY WORN
WORN
VERY WORN
UNREPAIRABLE
MARRED

Product Service

REPAIR CHARGE	25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

STOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
GER GROUP		B2			E1	F1
T ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5			E4	
OD		C1		D2	E5	F5
AL		C2				

FAULT

Trigger Assembly
Trigger Safety is partial
Left Hand 1966
Upon receipt safe is operative. Trigger will not reset.
Demonstration revealed that the action and trigger mechanism are generally sticky & binding. One trigger spring measured below minimum specifications. Sent in trigger assembly and stop screw, not responding to adjustment. Adjustments made satisfactorily. Rifle needs good cleaning.

COMMENTS

Replace trigger assembly & clean action at 1/2 normal replacement cost, as gesture of good will

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CC					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS00933