# RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R92-17282

| INITIAL | CUSTOMER ORDER NO. |
|---|---|
| FPS | 1962 |

| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
|---|---|---|---|---|---|
| 08/14/92 | 08/28/92 | DH 9-87 | B6891806 | | 700 30-06 RS |

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:

BILLS SPORTING GOODS
724 MAIN ST
LOMIRA WI 53048

SHIP TO:

BILLS SPORTING GOODS
724 MAIN ST
LOMIRA WI
53048

CUST NO:007455 ILION

| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE | PROM. DATE | ESTIMATED | VIA |
|---|---|---|---|---|---|
| | | ☐ CLEAN/TEST | | | UPS |

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [x] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

| | |
|---|---|
| REPAIR CHARGE | |
| EXCISE | |
| TAX | |
| INSURANCE | |
| UPS | |
| PARCEL POST | |
| TOTAL | |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|---|---|---|---|---|---|---|
| CYCLE | A1 | B1 | | | | |
| TRIGGER GROUP | "Fails on closing bolt and sometimes on moving safety" | B2 | | | E1 | F1 |
| BOLT ASSY. | | B3 | | | E2 | F2 |
| BARREL ASSY. | | B4 | | D1 | E3 | F3 |
| REC. ASSY. | | B5 | | D2 | E4 | F4 |
| WOOD | | | C1 | D3 | E5 | F5 |
| METAL | | | C2 | | | |

MAIN FAULT As above — someone has completely misadjusted the trigger assembly — 1) excessive over-travel 2) no retraction spring force (trigger pull is only 1½ pounds!)

rear-left .014"

PARTS

COMMENTS Quote new trigger assembly at ½ normal cost, as gesture of good-will. Tell customer to keep his hands off adjustments on new trigger assembly!!!

| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
|---|---|---|---|---|---|
| | | | | | |

| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |
|---|---|---|---|---|---|
| | | | | | |

OFFICE COPY

RD6925 REV. 1/92

PS01007