RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN FRED EMHOF

ORDER: R 92-24410

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/12/92	11/12/92	DX 9-73	6673330		700 6MM ADL

ACCESSORIES: W/STUDS SCOPE BASE

FROM:

BAKER, STAN
314 POWELL AVE
P O BOX 338
DUNN NC 28334

SHIP TO:

BAKER, STAN
314 POWELL AVE
P O BOX 338
DUNN NC 28334

CUST NO:070023 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
				UPS

WRITE ☐ CLEAN/TEST

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"Does gun fire several times without pulling the trigger"				E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Could not duplicate complaint. However it was noted that the trigger assembly had been adjusted outside factory (sealant missing on adjustment screws) and, the sear-engagement was insufficient. At times if the bolt was closed fast, the firing pin would not cock, but simply follow down on the cocking cam. Also, there is excessive oil and contamination in the trigger assembly.
Trigger pull 3½ pounds; sear-lift .008"

PARTS

COMMENTS: Based on condition of trigger assembly and the fact that the sear-engagement has been tampered with, offer new trigger assembly at ½ normal cost, as gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

PS01019