RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: JACK KAST Set up file

ORDER: R 94-26553

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
09/15/94	09/16/94	RS 11-69	6211702		700 22-250 BDL/VAR

ACCESSORIES: W/STUDS SCOPE BASE L/REAR SIGHT

FROM:
CARRUTHERS, WALT H.
119 CLARKSVILLE RD.
WILMINGTON OH 45177

SHIP TO:
CARRUTHERS, WALT H.
119 CLARKSVILLE RD.
WILMINGTON OH 45177

CUST NO:103661 C.O.DL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☑ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

9/16/94

incl's clean & test

REPAIR CHARGE	20.00
~~EXCISE~~	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

The cartridge fires when you flip the safety off. It also went off once when it closed the bolt.

MAIN FAULT: Mfgr. 11-69 Unable to duplicate customers concern as said, however the trigger adjusting screws have been altered outside of the factory! Not recommended! Exchange the trigger assy at a special price strictly as a gesture of good will

PARTS: Trigger Assy Complete

COMMENTS: trigger pull measured 1 1/4 to 1 3/4 LB as Rec'd. Sear lift was .0075

- Bolt Stop Sticks
- Bolt is Rusted
- Rust on bottom of Receiver
- Rust on trigger Assy.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS01410