RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-15686

INITIAL	CUSTOMER ORDER NO
FJB	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/24/92	08/04/92	PY 6-74	6763155		700 270 ADL

ACCESSORIES W/STUDS L/MAG SPRING L/FOLLOWER
L/ FLOOR PLATE

FROM:
FRANKS GUN SHOP
RD 1 BOX 695A
SALTSBURG PA 15681

SHIP TO:
FRANKS GUN SHOP
RD 1 BOX 695A
SALTSBURG PA 15681

CUST NO:005972 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"Sometimes upon closing the bolt, the firearm accidentally discharges"

MAIN FAULT Unable to duplicate complaint. Rifle operates normally – however disassembly revealed that the trigger assembly was quite dirty & contained an excess of oil.

trigger pull 4½ pounds; sear lift .0085"

PARTS

COMMENTS Offer to clean present trigger assy or install a new trigger assembly at ½ normal cost as a gesture of good will, if that would help restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTER

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/

PS02325