# RECEIVING AND ESTIMATING REPORT

COMMENTS: to Product Service

ORDER: R 93-17349

W/FLOOR PLATE, MAG BOX, MAG PG, FOLLOWER, SCREWS

| INITIAL | CUSTOMER ORDER NO. |
|---|---|
| JJM | V351641929 |

| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
|---|---|---|---|---|---|
| 08/16/93 | 08/25/93 | KU 5-71 | 6421105 | | 700 30-06 |

ACCESSORIES: L/WOOD

L/REAR SIGHT

FROM:

GARRISON, DONALD
600 W DIVISION ST
FT STOCKTON TX 79735

SHIP TO:

GARRISON, DONALD
600 W DIVISION ST
FT STOCKTON TX
79735

CUST NO: 082483 CJO.D

| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE | PROM. DATE | ESTIMATED | VIA |
|---|---|---|---|---|---|
| | | | | 8-27 | V351661529 |

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [x] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

Ship to: Elk Hawk

| | |
|---|---|
| REPAIR CHARGE | |
| EXCISE | |
| TAX | |
| INSURANCE | |
| UPS | |
| PARCEL POST | |
| TOTAL | |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|---|---|---|---|---|---|---|
| CYCLE | A1 | | | | | |
| TRIGGER GROUP | [illegible] | [illegible] | | [illegible] closing + hard weight + [illegible] | | |
| BOLT ASSY | | | | | E2 | F2 |
| BARREL ASSY | | B4 | | D1 | E3 | F3 |
| REC ASSY | | B5 | | D2 | E4 | F4 |
| WOOD | | | C1 | D3 | E5 | F5 |
| METAL | | | C2 | | | |

MAIN FAULT: Rear engagement screw tampered with outside factory.

Disposition per [illegible] - Replace trigger assembly w/ new one at special price of $12.50 also clean + test. Ship prepaid to above address - Total chg. $12.50 DTC/RKP

→ strictly at gest of goodwill

| PARTS | COMMENTS |
|---|---|
| | |

| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
|---|---|---|---|---|---|
| | | | | | |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |

RD6925 REV. 1/92

PS02702