RECEIVING AND ESTIMATING REPORT

COMMENTS: Stekl

ORDER: R 92-02761

INITIAL	CUSTOMER ORDER NO.
FPS	3192R

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/15/92	00/00/00	XJ 12-89	C6484115		700 30-06 BDL

ACCESSORIES: W/STUDS

FROM:
GRICE WHOLESALE
216 REED ST
PO BOX 1028
CLEARFIELD PA 16830

SHIP TO:
GRICE WHOLESALE
216 REED ST
PO BOX 1028
CLEARFIELD PA 16830

CUST NO:005411 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

will fire when safe released when temp 20° or lower

MAIN FAULT: Trigger assembly is rusted - rust on exterior of housing and on inner surfaces - internal parts are not moving freely too properly. Front of bolt face is rusted also. Bore of barrel contains rust also. This rifle has not been properly maintained

PARTS

COMMENTS: Offer replacement trigger assembly at ½ original cost as a gesture of good-will.

When rifle is returned, explain on owners warranty and outline maintenance section!!

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD0905 REV. 8 91

PS02715