RECEIVING AND ESTIMATING REPORT

COMMENTS: W/HUNTER FIBERGLASS STOCK

ORDER: R 92-04606

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/03/92	02/06/92	PH 6-87	B6867503		700 270

ACCESSORIES: W/STUDS

FROM:
GRAMKE, KORBY
6029 W 38TH SO CT
WICHITA KS 67215

SHIP TO:
GRAMKE, KORBY
6029 W 38TH SO CT
WICHITA KS 67215

CUST NO:057759 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- [x] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1 Fired	B1 when	safety	was	disengaged	
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Could not duplicate complaint — trigger assembly operates properly. However, safety "off" force required does appear to be high for some reason.

Trigger pull 5½#, sear-lift .0115"

PARTS

COMMENTS: Replace trigger-safety assembly at no-charge as gesture of good-will, even though rifle is 4½ years old

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
AB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PS02719