RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: JACK KAST

ORDER: R 94-16301

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
05/19/94	05/20/94	EM 10-92	S6217973		700 338 WIN MAG/ADL/SS

ACCESSORIES: W/STUDS

FROM:
HERBERT, GORDON
1924 E. SPRINGER
GUTHRIE OK 73044

SHIP TO:
HERBERT, GORDON
1924 E. SPRINGER
GUTHRIE OK 73044

CUST NO:097598 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	20
EXCISE	
TAX	
INSURANCE	
UPS	8
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

When I take it from safety to put it into firing position it will fire some times without pulling the trigger.

MAIN FAULT Mfgr 11-92 Unable to duplicate customer concern as recd. Trigger pounds pull and overtravel screws have been altered outside of the factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at a special price strictly as a gesture of good will.

PARTS

COMMENTS trigger pull measured 2 1/2 to 2 3/4 lbs as recd. sear lift was .013

magazine follower binds on bolt

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS03172