RECEIVING AND ESTIMATING REPORT

COMMENTS: STAINLESS STEEL

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
03/21/91	03/26/91	PS 6-69	6248783	700 7MMMAG BDL	R 91-07875

ACCESSORIES: W/STUDS

FROM:
J T'S GUN & PAWN SHOP
209 MAIN ST
HAZARD KY 41701

SHIP TO:
J T'S GUN & PAWN SHOP
209 MAIN ST
HAZARD KY 41701

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: Fires when safe is released - wants price to rebblue

MAIN FAULT: stainless steel bbl - we do not rebblue anymore
trigger not moving freely — trigger assembly is contaminated with sticky substance — internal fitting, appears to have been disassembled outside of factory and improperly re-assembled — firing pin assembly is not properly fitted and is binding trigger.

PARTS: Clean present trigger assembly, if possible, if not, quote new trigger assembly at ½ normal cost as gesture of good will.

Properly re-assemble rifle at completion of service.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS03302