RECEIVING AND ESTIMATING REPORT

COMMENTS: WOG 2 OF 2 W/MUZZLE BRAKE — Stekl

ORDER: R 92-08386

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
03/16/92	03/26/92	AO 3-77	A6426359		700 30-06	BDL

ACCESSORIES: W/STUDS

FROM:
L'ARMURIER ALAIN BOUCHARD
420 ROUTE 143
ULVERTON QUEBEC
CANADA
J0B 2B0

SHIP TO:
L'ARMURIER ALAIN BOUCHARD
420 ROUTE 143
ULVERTON QUEBEC
CANADA
J0B 2B0

CUST NO:007647 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
				4-1-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Shoots when putting off safety.

MAIN FAULT: Unable to duplicate complaint — However trigger assembly has been tampered with outside factory, as evidenced by sealant missing from adjusting screw and screw slot upset — firing pin sometimes follows down upon closing bolt.

Trigger pull 4 pounds; sear lift .0265"

PARTS

COMMENTS: Offer replacement trigger assembly at ½ normal cost, as gesture of good will.
Sear engagement altered outside factory.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBB					

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PS04007