RECEIVING AND ESTIMATING REPORT

COMMENTS: L/FLOOR PLATE, SCREWS W/BTM OF SCOPE BASE

ORDER: R92-15501

STEKL

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/22/92	07/31/92	CO 4-77	A6446906		700 270 WIN

ACCESSORIES: L/WOOD L/FOLLOWER L/MAG SPRING L/REAR SIGHT

FROM:
LINGO, JOE A JR
P O BOX 424 CR-321
SWEENY TX 77480

SHIP TO:
LINGO, JOE A JR
P O BOX 424 CR-321
SWEENY TX 77480

CUST NO:064339 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		8/3/92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

rifle malfunctioned upon moving safety lever from safe to fire.

MAIN FAULT: No fault found - unable to duplicate complaint.

Trigger pull - 4 Pounds; sear lift - .005"

PARTS

COMMENTS: Offer to return rifle as-is, or, to install new trigger assembly at no charge, as gesture of good will, if that will better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
LRO					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

PS04022