**IVIN : AND ESTIMATING REPORT**

CUSTOMER ORDER NO.

COMMENTS: Product Service

ORDER: R 94-23527

| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
|---|---|---|---|---|---|
| 08/12/94 | 08/12/94 | | 230602 | | 700 30-06 DEER |

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:

MIKSATKO, LOUIS
1018 N. DULUTH
THIEF RIVER FALLS MN 56701

Set up File

SHIP TO:

MIKSATKO, LOUIS
1018 N. DULUTH
THIEF RIVER FALLS MN 56701

CUST NO:101404 C.O.D

| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE | PROM. DATE | ESTIMATED | VIA |
|---|---|---|---|---|---|
| 063103 | | ☐ | | | UPS |

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

8/25/94

| | |
|---|---|
| REPAIR CHARGE | 20.00 |
| EXCISE | |
| TAX | |
| INSURANCE | |
| UPS | 8.00 |
| PARCEL POST | |
| TOTAL | 28.00 |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|---|---|---|---|---|---|---|
| CYCLE | A1 | B1 | | | | |
| TRIGGER GROUP | | Gun went off when unloading | | | | F1 |
| BOLT ASSY. | | B3 | | | E2 | F2 |
| BARREL ASSY. | | B4 | | D1 | E3 | F3 |
| REC. ASSY. | | B5 | | D2 | E4 | F4 |
| WOOD | | | C1 | D3 | E5 | F5 |
| METAL | | | C2 | | | |

MAIN FAULT: Mfgr 1966 Unable to get gun to malfunction as rec'd. trigger pull had the pounds pull and the overtrave screws adjusted outside of the factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at a special price strictly as a gesture of good will.

PARTS

COMMENTS: trigger pull measured 3 to 3 1/4 LB. as rec'd. sear lift was .0105

Rust inside of trigger housing

| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
|---|---|---|---|---|---|
| T.A.L. | | ✓ | ✓ | | |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |

OFFICE COPY

RD6925 REV. 1/94

PS04207