RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.

COMMENTS: WOG 1 OF 2
W/15 LIVE RDS Federal

ORDER: R 94-33471

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/18/94	11/22/94	KO 5-94	C6887567		700 243 BDL/VAR

ACCESSORIES: W/STUDS

FROM:
PLAZA JEWELRY GUNS/PAWN
310 S BICKETT BLVD
LOUISBURG NC 27549

SHIP TO:
PLAZA JEWELRY GUNS/PAWN
310 S BICKETT BLVD
LOUISBURG NC 27549

CUST NO:046440 C.O.D

ACCOUNT NUMBER: 063103
ACCOUNT NUMBER N/C
WRITE ☐
PROM. DATE
ESTIMATED
VIA: UPS

GUN CONDITION
- [x] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

11/29

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	$ 50.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1		C		
TRIGGER GROUP		Blew back in customer face				
BOLT ASSY.		B3			E3	F2
BARREL ASSY.		Gunsmith checked headspace - said it was off				
REC. ASSY.		B5		D2	E4	F4
WOOD		Gun would fire when operating the bolt				F5
METAL			C2			

MAIN FAULT: Mfgr. Stff Bolt face damaged as rec'd, ejector stuck in bottom of hole, Appears that damage was caused by removing a overpressure round from the bolt face. Bolt will not close on No Go gage (Headspace OK). TRIGGER HAS BEEN ADJUSTED outside of Factory, would not fire when operating bolt as rec'd. Repair at a special price strictly as a gesture of good will. [redacted]

PARTS: Breech Bolt Assy
~~Trigger~~
TRIGGER Guard

COMMENTS: Trigger pull measured 3 3/4 LBS as rec'd sear lift was .013
[redacted]
TRIGGER Guard Bent as rec'd
* No incident case supplied
Readjust & pull screw & reseal

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/94

Please Above, orig. Box of Ammo Excess

NORTH CAROLINA SALES OFFICE
MT. HOLLY, N.C.
(704) 827-4060 FAX (704) 827-4060

SOUTH CAROLINA SALES OFFICE
LITTLE MOUNTAIN, S.C.
(803) 345-6602 FAX (803) 345-6608

TOTAL WEIGHT 22.48 # PKGS: 1

INVOICE TOTAL 348.43

PAY THIS AMOUNT

STATEMENT RENDERED ONLY BY REQUEST

PS04928