RECEIVING AND ESTIMATING REPORT

COMMENTS: CUST NO:052054 C.O.D [redacted] NOT OUR MFG

INITIAL	CUSTOMER ORDER NO.
CS	

DATE RECEIVED	DATE OPENED	DATE CODE	NUMBER	MODEL AND GRADE	ORDER
0/28/91	10/31/91		A[redacted]98040	700 243 ADL	R 91-22003

ACCESSORIES: W/STUDS SCOPE BASE

FROM:
POLUPSKY, CLIFFORD
1821 DOREGON
GRAND FORKS AFB ND 58204
USA

SHIP TO:
POLUPSKY, CLIFFORD
1821 DOREGON
GRAND FORKS AFB ND
USA 58204

ACCOUNT NUMBER	ACCOUNT NUMBER N/C		PROM. DATE	ESTIMATED	VIA
		WRITE ☐ CLEAN/TEST			UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ MARRED

CUSTOMER'S REQUEST: 1.) "My 700 has fired upon closing of the bolt and also when put on fire." 2.) "Has trouble chambering from a full magazine 3.) Please send owner's manual & catalog

GUN FAULT: 1.) Trigger assembly has been improperly adjusted outside factory (foreign talent on all adjusting screws) - excessive over-travel, insufficient sear-engagement so closing of bolt causes firing pin to fall. 2) Rifle has been re-barreled and highly modified — improper magazine box - follower has been ground also. Trigger pull 3½#; Sear-lift .008"

PARTS: 1.) send quotation for new trigger assembly
2) " " " proper magazine parts.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS05019