RECEIVING AND ESTIMATING REPORT

COMMENTS: SJEKL

ORDER: R 92-11978

INITIAL: JJM | CUSTOMER ORDER NO.:

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
05/15/92	05/26/92	PA 6-80	B6225317		700 30-06	ADL

ACCESSORIES

FROM:
RENNICK, R J
9555 BROWN
BEAUMONT TX 77707

SHIP TO:
RENNICK, R J
9555 BROWN
BEAUMONT TX 77707

CUST NO: 062197 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	gun will fire when bolt is closed	B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: As received, trigger assembly and bolt stop were inoperative. Disassembly of rifle revealed trigger assembly above contaminated with a gummy substance which did not allow the bolt stop lever or safe-safety cam to move — the rifle would not cock upon closing the bolt. The spring pin simply followed down. Improper Maintenance

PARTS	COMMENTS
	Send quote for thorough cleaning and new trigger assembly (± normal cost, as gesture of good-will)

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
EB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92

PS05077