Remington Arms Co., Inc.
Product Service
Legal Case #:7607

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
265420	4/20/2012	4/23/2012	4/23/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Adam	Lowery	1307 Airport Rd, Ste 3A	Brandon	MS	38047		E adam@loweryinsurance.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance			
S Fires when going from safe to fire	Concern:1007 Fired on Safe Release		Unknown	
C				

5/9/12 Per note on SR, gun fires when going from safe to fire.cm

---

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	6657267	OX	6/1/1973
Date Purchased	**Where Purchased**	**Accessories**	**Original Owner**			
	JERRYS SPORT SH OLYPHANT PA	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM price						

	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	5/9/2012				

5/9/12 Per Ilion, trigger assm dirty and some light rust. Trigger is binding. Replace TPA, clean, test at BLSM price.cm

---

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		4/23/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
	Description		22" 270 WIN
	Date Code		OX
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,LITE RUSTING
	Pull	---Select---	10+#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Service Request

Remington Service
PO Box 700
Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. Thi serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS YOUR RECORDS.

Service Request Numb&rrial Number / Description	Date of Request 03/22/2012
SR00015841 · 6657267	Date Printed 03/22/2012
Model 700	

760?

Customer:
ADAM LOWERY
1307 AIRPORT RD SUITE 3A
BRANDON, MS 38047 US

Email: adam@loweryinsurance.com

Destination:
Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return:
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
Gun fires when going from safe to fire

Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount

Serial Number: **6657267**
Model: **700**

RE00265420

*T.A. dirty + some like rust.
Trig. is Binding. Nep Wac TPA,
Clean Test under BCP Ron
820. +

Quote*

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	$.00

PS 28429

PS 28430

PS 28432