DATE 12-10-65 MODEL 600 M Cal./Ga. 6.5mm mag GUN NO. 56115 Sheet No. 1

DESCRIPTION OF TEST: Function

Total Rds. Fired
Total Malfunctions
Rate

AMMUNITION	Shooter	No. of Rds.	MALFUNCTIONS: Firing	Extraction	Don't Blow Back	Ejection	Locking Open	Feed from Mag. 1st Latch	Feed from Mag. 2nd Latch	Double Feed From Magazine	Dropped Shell	Failed to Trip Carrier Latch	Stem Carrier	Stem Chamber High	Stem Chamber Low	Stem Chamber Rt.	Locking Up	Loading	Breakages	Replacement	Gun Failure	Adjustments	REMARKS: New Release point cuts in rail
120gr. PSPCL	U	—																					could not close bolt
																							Returned to H. Wuttemann
																						✓	Front guard screw was to long - put back in test
120gr. PSPCL	U	4																					
		4																					
		4																					
		4																					
		4																					
																							Action sometimes a little tight

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER
KINZER V. REMINGTON