PREVIOUS ROUNDS

DATE 6/15/79 MODEL 700 Cal 30-06 GUN NO. A 6794647

Total Rds. Fired

Total Malfunctions

Rate

Description of Test Ruritan extractor

AMMUNITION	Shooter	No. of Rounds	MALFUNCTIONS: Firing	Extraction	Ejection	Trapped Shell	Don't Lock Up	Don't Lock Open	Stem Chamber: High	Stem Chamber: Low	Stem Chamber: Right	Shell Stems Mag.	Bolt Override	Bolt Catches Follower	Shell Jumps Mag.	Action Binds	Don't Blow Back	Follower Binds			Breakages	Adjustments	REMARKS
P30063	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				
	SF	20	OK																				

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER
KINZER V. REMINGTON