Report No. 890202

RESEARCH TEST & MEASUREMENT LAB WORK REQUEST

	AREA OF TESTING		
___ Developmental	___ Safety Related	___ Litigation	
X Design Acceptance	___ Competitive Evaluation	___ Warehouse Audit	
___ Pre-Pilot	___ New Design	___ Cost Reduction	
___ Pilot	X Design Change	Stake ___	
___ Production Acceptance	___ Plant Assistance	___ Other	

FIREARM STAT'S.	REPORT REQ'D.	
MODEL: XP-100	FORMAL X	DATE REQUESTED: 1-20-89
CAL. or GAGE: .35 Rem	TEST RESULTS ONLY ___	DATE NEEDED BY: A.S.A.P.
BARREL TYPE: ___		REQUESTED BY: F. MARTIN
PROOFED: YES X NO ___		WORK ORDER NO: ___

TEST TYPE

___ Strength Test	___ Ammunition Test	___ Dry Cycle Test	___ Photo/Video
X Function Test	___ Environmental Test	___ Measurements	___ Other ___
___ Accuracy Test	___ Customer Complaint	X Endurance Test	___

EXPLAIN IN DETAIL THE REASON FOR THIS TEST: 3-5 Gun Samples To Be Tested As Follows

1 Each Sample Dry Cycle (50,000 each)

3 Each Sample Shoot 2000 Rnds To Test And Evaluate New Trig Adjusting Screw/Lock Nut Assembly

Measure Sear Engagement At Start Of Test And Every 500 Dry Cycles And Every 200 Rounds

GUNS REQUIRED:

To Be Supplied

NOTE: NO firearms or parts will be tested in the Labs unless they are accompanied by a Work Request, and both are delivered to the Labs by the designer or engineer. All Work Requests are to be filled out in detail. No Exceptions.

DATE COMPLETED: ___

TEST COMPLETED BY: ___

REPORT DATE: ___



Measure seal eng. every 500 cycles for first 3000 cycles. Then every 2000 cycles for rest of test.

meas. seal eng. every 200 Rds for 1st 1000 Rds. Then at 1500 Rds. and 2000 Rds

DRY CYCLE

Measure 500 cy seal eng.	to 3000
1000 cy	to 10,000
2000	20,000
5000	50,000