RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 91-26294

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
12/11/91	12/17/91	LW 2-72	6524075		700 25-06	BDL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:
ARMBRUSTER, DUANE
RR 1 BOX 96A
FALLS CITY NC 68355
USA

SHIP TO:
ARMBRUSTER, DUANE
RR 1 BOX 96A
FALLS CITY NC 68355
USA

CUST NO:054846 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4				F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Rifle fired when safety was moved to the fire position and also when bolt was being lifted.

MAIN FAULT Unable to duplicate above complaints. Many attempts were made to make the rifle malfunction in these ways, without success. It was noted however, that the trigger assembly is oily and dirty, and that the trigger pull has been adjusted outside factory to 2½ pounds. This is below our min. spec. Sear-left .0085"!

PARTS

COMMENTS Offer to clean & re-set present trigger assembly, or, we can offer a new [redacted] trigger assembly at the normal cost as a gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JJB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91