RECEIVING AND ESTIMATING REPORT

COMMENTS: Steel

ORDER: R 92-24470

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/10/92	11/13/92	CG 4-86	B6782921		700 30-06 MTN

ACCESSORIES: W/STUDS

FROM:
B & S INDUSTRIES
4427 SPRUILL AVE
N CHARLESTON SC 29406

SHIP TO:
B & S INDUSTRIES
4427 SPRUILL AVE
N CHARLESTON SC 29406

CUST NO:006054 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		12-1-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Fires when taking safety off.

MAIN FAULT: Unable to duplicate complaint. Rifle and trigger assembly oper normally in every respect.

Trigger pull 5½ pounds; sear lift .015"

PARTS

COMMENTS: Offer following option:

1.) To return rifle as-is;

2.) To install new trigger assembly at ½ normal cost, as a gesture of good-w if that will better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6825 REV. 1