RECEIVING AND ESTIMATING REPORT

STAINLESS/CUSTOMER REMOVED BLUEING

R ORDER 94-13175

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/14/94	04/15/94	PU 6-71	6445063		700 17 REM BDL

ACCESSORIES W/STUDS L/SIGHTS

FROM:

BUTTON, DENNIS
13860 GILLETTE RD
ALBION NY 14411

SHIP TO:

BUTTON, DENNIS
13860 GILLETTE RD
ALBION NY
14411

CUST NO:096024 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

~~Sent quote~~

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						F1
BOLT ASSY.		B3			F2	F2
BARREL ASSY.						F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Fires on safe release usually after shooting set for a long period of time

MAIN FAULT Mfgr. 6-71 Unable to duplicate customer concern as said. Trigger pull and overtravel adjusting screws were altered outside of factory, sear was gummy and sticking in housing. Exchange trigger assy. at special price as gesture of good will and to restore customer confidence in rifle.

PARTS

COMMENTS Trigger pull measured 4½ to 6# as rec'd. sear lift was .010

Bluing has been removed from all Assy

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JRL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94