RECEIVING AND ESTIMATING REPORT

ORDER R 94-12944

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/13/94	04/13/94	RI 11-88	A6381678		700 300 WIN MAG/BDL

ACCESSORIES W/STUDS

FROM:

CAMBURN, BOB
1039 WEST AVE
OCEAN CITY NJ 08226

SHIP TO:

CAMBURN, BOB
1039 WEST AVE
OCEAN CITY NJ 08226

Fred
Zippy

CUST NO:095878 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

COD

REPAIR CHARGE	80.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2	E4	
WOOD			C1	D3	E5	F5
METAL			C2			

Purchased rifle used, intend get it done.
Protected safety, safe moved to fire position, the rifle would fire.

MAIN FAULT Rifle Mfg. Nov 1988 Could not duplicate concern, however upon receipt, trigger working very sluggish, Gunsmiter found action and trigger assembly coated with a heavy gunge substance. Bolt stop also not working.

PARTS

COMMENTS Replace complete trigger assembly with N/S (customer report) and clean action at 1/2 normal cost as gesture of good will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CC		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94