RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN JACK KAST

ORDER: R 94-16213

INITIAL	CUSTOMER ORDER NO.
JJM	✓

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
05/18/94	05/19/94	ED 10-77	A6670683		700 BMMAG BDL

ACCESSORIES

FROM:
CAMP, STEVE
RR #2 SITE 5 BOX 27
WINTERBURN
ALBERTA TOE 2N0
CANADA

SHIP TO:
CAMP, STEVE
RR #2 SITE 5 BOX 27
WINTERBURN
ALBERTA TOE 2N0
CANADA

CUST NO:095440 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	059015	☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.						
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2		
WOOD			C1	D3	E5	F5
METAL			C2			

Brass cracked on factory test fired in this rifle and the rifle fired upon closing the bolt. Fax for approval of these as any cost

MAIN FAULT: Mfgr. 16-77 Unable to duplicate customers concern of fire on bolt closing after cycling bolt vigorously numerous times with safe in fire position. Took trigger Assy. apart and found gummy residue on sear, connector and inside of housing, no other fault found. Exchange trigger Assy. at N/C as a gesture of good will and to restore customer confidence in the rifle. All metal parts should be maintained with a light film of light oil.

PARTS	COMMENTS
Trigger Assy Complete with Bolt Lock	Trigger pull measured 4 3/4 #. as rec'd. Sear lift was .0155

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94