RRR-59 - 3-3

4

[illegible]: VS	[illegible]: 538	[illegible]: 700 BDL	
[illegible]: FLIR		[illegible]: 3 4528	
[illegible]: SCOPE SCREWS REQUIRED		[illegible]: 10-22-81	
		[illegible]: CHARLIE: SPT GOODS 7401 H-MARINE [illegible] VA [illegible]	
[illegible]: NOT KNOWN			
[illegible]:		[illegible]: A6434157	
[illegible]: R	[illegible]: 9 [illegible]: 111	[illegible]: 0 C 7-78	
[illegible]: OK		[illegible]: 270	
[illegible]: OK		[illegible]: M-[illegible]	
[illegible]: OK		[illegible]: [illegible] 11/19/8	
[illegible]:		[illegible]: [illegible] 11/17/81	
[illegible]:		[illegible]: [illegible] 11-19-81	
		[illegible]: [illegible] 11/19/81	
[illegible]: (Damaged, Stolen, Old Style)		[illegible]: [illegible]	

SLIGHT SCRATCHES ON RIGHT SIDE OF STOCK

[illegible]: FIRED WHEN SAFETY WAS REMOVED

[illegible]:

[illegible]: Unable to duplicate customer complaint. All-4 Trigger Pull Power trick test. .009 [illegible]

Replace trigger control - No charge. [illegible]