RECEIVING AND ESTIMATING REPORT

COMMENTS

TIAL	CUSTOMER ORDER NO.
PS	

TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
4/24/91	04/25/91	LI 2-88	C6231502	700 308 WIN POL	R 91-09844

CESSORIES W/STUDS SCOPE BASE

ROM:
TPR. DYWINSKI, LEON SFI
NEW YORK STATE POLICE
4525 W SAILE DR
BATAVIA NY 14020

SHIP TO:
TPR. DYWINSKI, LEON SFI
NEW YORK STATE POLICE
4525 W SAILE DR
BATAVIA NY 14020

COUNT NUMBER	ACCOUNT NUMBER N/C		PROM. DATE	ESTIMATED	VIA
		WRITE ☐ CLEAN/TEST			UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST "When the safety is on the bolt is able to be cocked. When the safety is released the firing pin goes forward".

AIN FAULT As received, the firing pin followed-down when the bolt was closed. Disassembly revealed the trigger assembly was rusted from unknown cause, causing the internal trigger parts to not move freely.

RTS

Replace trigger assembly at no-charge, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 7/90