RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN FRED EMHOF

INITIAL	CUSTOMER ORDER NO.
JM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
1/16/90	11/19/90	KY 5-74	6748705	700 30-06 BDL	R 90-30274

ACCESSORIES: W/STUDS

FROM:
FOOTHILL'S SHOOT CTR
7860 W. JEWELL AVE.
LAKEWOOD CO 80226

SHIP TO:
FOOTHILL'S SHOOT CTR.
7860 W. JEWELL AVE.
LAKEWOOD CO
80226

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "The customer claims the gun fired by itself"

FAULT: Cannot duplicate complaint; or make with otherwise malfunction. However, sealant has been removed from all adjusting screws, outside factory. Overtravel is excessive, trigger pull 3#

PARTS: Offer to replace trigger assembly at ½ normal price, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

16925 REV. 7/90