RECEIVING AND ESTIMATING REPORT

COMMENTS: Product Service

ORDER: R 94-01477

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/11/94	01/12/94	WR 8-68	121599		660 308

ACCESSORIES: W/STUDS SCOPE BASE

FROM: F. Supry
FORBES, JAMES L
P O BOX 1153
MOREHEAD CITY NC 28557

SHIP TO:
FORBES, JAMES L
P O BOX 1153
MOREHEAD CITY NC 28557

CUST NO:090471 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				2-18-94	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	20.00
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.						
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: "Will not fire, then other times it will fire when the bolt is closed"
Upon weight safety would not engage.
Examination reveals that the trigger assembly has been taken apart and not reassembled properly. The safety detent ball was lost. Allow one notice the safety.

PARTS

COMMENTS: Replace complete trigger assembly & check action at 1/2 normal replacement cost, or better if good used

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
R.B.S.					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92