RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 94-12564

INITIAL	CUSTOMER ORDER NO.
RJB	008813

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/11/94	04/11/94	XT 12-70	3657724		700 264 WIN MAG/SS

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:

HANLON, JAMES
RR 1 RT 104
PO BOX 33
MANTVILLE NY 13111

SHIP TO:

HANLON, JAMES
RR 1 RT 104
PO BOX 33
MANTVILLE NY 13111

CUST NO:095658 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			DOOR

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☑ MARRED

Product Service

REPAIR CHARGE	20
EXCISE	
TAX	
INSURANCE	
UPS	8
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.						F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Fired when safety is released also when in the position when the bolt is touched

MAIN FAULT Mfg. 12-70 Unable to duplicate customers concern as well. Trigger pull and trigger overtravel screws have been adjusted outside of the factory and the sear was gummed up in housing. We do not recommend that the trigger be adjusted outside the factory and metal parts should be lubricated periodically with a light coat of light oil. Replace trigger assy. at special price strictly as a gesture of good will.

PARTS

COMMENTS Trigger pull measured 5 to 5 1/2 LBS as received. sear lift was .009
- Sear sticks in housing
- Bolt stop sticks

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CC					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94