RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 94-11267

INITIALS CUSTOMER ORDER NO.

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
[redacted]/94	[redacted]/29/94	WD 8-83	B6487237		700 30-06 BDL

ACCESSORIES W/STUDS SCOPE BASE

Full Supply

FROM:

HANLON, THOMAS P
RR 4 BOX 75A
DETROIT LAKES MN 56501

SHIP TO:

HANLON, THOMAS P
RR 4 BOX 75A
DETROIT LAKES MN 56501

CUST NO:095035 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
068103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

X-Ray guard screw loose as well
Product Service
BD

REPAIR CHARGE	15.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	23.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1 Shot off on its own when safety was removed					
TRIGGER GROUP		B1			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Mfgr. 8-83 Unable to duplicate customers concern as well. Trigger pounds pull has been adjusted outside of factory. Replaced trigger assy. at a special price strictly as a gesture of good will and to restore customers confidence in rifle.

PARTS Trigger Assy.

COMMENTS: Trigger pull measured 3 1/2 LBS as received. Sear lift was .012

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CC		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94