RECEIVING AND ESTIMATING REPORT

ORDER R92-15247

W/BI POD ATTN: Fran Cole

INITIAL	CUSTOMER ORDER NO.
PS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/17/92	07/29/92	WQ 8-78	A6614783		700 308 WIN BDL VAR

ACCESSORIES W/STUDS SCOPE MNTS. SCOPE BASE L/REAR SIGHT

FROM:

HYDE, JOHNNY
PALM BEACH COUNTY SHERIFF
3228 GUN CLUB RD
WEST PALM BEACH FL 33406

SHIP TO:

HYDE, JOHNNY
PALM BEACH COUNTY SHERIFF
3228 GUN CLUB RD
WEST PALM BEACH FL 33406

CUST NO:064201 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST			UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
SEC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"... when he moved the safety from the safe position into the firing position, the gun went off."

MAIN FAULT No fault found. Cannot duplicate complaint. Safety and trigger assembly operate properly in every way.

Trigger pull 4 pounds → see-left .0095"

PARTS

COMMENTS Offer to settle return offer is, to replace trigger assembly with a new one at normal price, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1