RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R91-23325

INITIAL	CUSTOMER ORDER NO.
FPS	RV51617

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/12/91	11/15/91	DI 9-88	C6303917		700 30-06 LH BDL

ACCESSORIES W/STUDS

FROM:
L.L.BEAN
ACCOUNTING DEPT
CASCO ST
FREEPORT ME 04033
USA

SHIP TO:
L.L.BEAN
RETAIL STORE
MORSE ST
FREEPORT ME
USA 04033

CUST NO:033352 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

1) The bolt release button sticks & allows the bolt to drop out when it should not
2) The firearm has discharged twice when the safety was pushed off

MAIN FAULT Trigger assembly has rusted from unknown source - internal trigger parts not moving freely nor properly

PARTS	COMMENTS
	1) repair bolt stop
	2) replace trigger assembly at N/C as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTEF

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8