RECEIVING AND ESTIMATING REPORT

COMMENTS: W/LEUPOLD SCOPE

ORDER: R 94-16361

INITIAL: FDC | CUSTOMER ORDER NO.:

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
05/20/94	05/20/94	CK 4/90	C6534027		700 30-06	SPRG.

ACCESSORIES: W/STUDS SCOPE MNTS SCOPE BASE L/SIGHTS

FROM:
LANUNZIATA, LOUIS J.
1700 RIVERVIEW DR.
P.O. BOX 1718
BURGAW NC 28425

SHIP TO:
LANUNZIATA, LOUIS J.
1700 RIVERVIEW DR.
P.O. BOX 1718
BURGAW NC 28425

CUST NO 1097632 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Customer said "I put the bolt back, and when I unpack the rifle"

MAIN FAULT: Rifle fully FNG — Could not duplicate the customer's problem. Gunsmith did point that the trigger adjustment and sear engagement screws have had the contact surfaces and have been re-set. Trigger pull — 2½ lb is between min. specification. Also found a metal shavings on the trigger housing which is due assembly the other safety concern.

PARTS

COMMENTS: Gunsmith not interested.

Replace complete trigger assembly and then return at his normal cost, as failure of good cause.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

to A/S
5/25/94