BARBER - Kinzer PPS GAL RE0002980

RECEIVING AND ESTIMATING REPORT

COMMENTS: WOOD IS MARRED

ORDER: R91-24393

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/22/91	11/26/91	PD 6-83	B6464290		700 7MMMAG BDL

ACCESSORIES: W/STUDS SCOPE BASE

FROM:
LEROY, KEN
716 DEPOT LANE
SULTAN WA 98294
USA

SHIP TO:
LEROY, KEN
716 DEPOT LANE
SULTAN WA
USA 98294

CUST NO:053714 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.					E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

1) Fires when bolt is closed with safety on.
2) Bolt release sticks

MAIN FAULT: Unable to duplicate complaint in factory. However, trigger assembly and bolt stop are contaminated by the gummy sticky substance. Internal trigger parts and working surfaces of gear-safety cam is sticking to guide plate of trigger assembly. Bolt stop is sticking also. Bottom of action does have oil concentration.
Trigger pull - 4 pounds; rear - 1½ oz

PARTS	COMMENTS
	Clean present trigger assembly, if possible; if not, offer to replace with new trigger assembly at ½ normal cost as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTER
KTB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/

BARBER - Kinzer PPS GAL RE0002980