RECEIVING AND ESTIMATING REPORT

COMMENTS: STAINLESS STEEL

ORDER: 92-10689

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/20/92	04/27/92		6711779		700 17REM BDL

ACCESSORIES: W/STUDS L/SIGHTS

OZ 7-75 2ND TIME

FROM:
MASCHMEDT & ASSOCIATES INC
12304 32ND AVE NE
SEATTLE WA 98125

SHIP TO:
MASCHMEDT & ASSOCIATES INC
12304 32ND AVE NE
SEATTLE WA 98125

CUST NO:060617 CJO.DL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"...	B2	"...kno discharged as the bolt	E1	"...ds closed".	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Trigger assembly has ejected from unknown source — internal parts are not moving freely nor properly. Complaint could not be duplicated, however, it is very possible that safety combination could at times cause this problem. Rifle has not been properly maintained

PARTS

COMMENTS: Replace trigger assembly at no charge, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JB3					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9