RECEIVING AND ESTIMATING REPORT

COMMENTS: to Product Service

ORDER: R 94-12201

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/06/94	04/07/94	DT 7-70	6358541		700 7MM MAG BDL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

F. Murray

FROM:

MCCARTY, DARWIN
2303 ASPEN DRIVE
ALAMOGORDO NM 88310

SHIP TO:

MCCARTY, DARWIN
2303 ASPEN DRIVE
ALAMOGORDO NM 88310

CUST NO:095516 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☑ MARRED

*Receiver area and bbl channel are glass bedded.
* other than adjustments, gun has been well maintained and clean

REPAIR CHARGE	15.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	23.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		I put the safety on off and it has fired				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Mfgr. 7-70. Unable to duplicate customer complaint as rec'd. All trigger adjusting screws have been altered from factory setting. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at a special price strictly as a gesture of good will and to restore customers confidence in the rifle.

PARTS

COMMENTS: Trigger pull measured 2 1/2 - 3 lbs as rec and Sear lift was .0075

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94