RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: KEVIN CORNELL

ORDER: R93-25432

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
EPS	8299	11/24/93	11/24/93		6540891		700 22-250 ADL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
MISCH, DON
RR 1
BOX 26
HUBBARDSVILLE NY 13355

SHIP TO:
MISCH, DON
RR 1
BOX 26
HUBBARDSVILLE NY 13355

CUST NO:087769 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐			DOOR

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

Gun purchased used, trigger pull very light, will fire w/out pulling trigger when safety lever is moved to fire"

REPAIR CHARGE	$25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	D1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Upon receipt, rifle inoperative. Examination revealed, trigger adjustment screw had been tampered w/ outside of the factory. Original, clear factory sealant has been replaced w/ a red colored, unknown substance. Action needs to be cleaned

PARTS

COMMENTS: Replace complete trigger assembly + clean action, at 1/2 retail replacement cost, as a gesture of goodwill

Go ahead per phone

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

1/92