RECEIVING AND ESTIMATING REPORT **BARBER - Kinzer PPS GAL RE0003459**

COMMENTS: W/RAM LINE STOCK ATTN JACK KAST

ORDER: R 94-16184

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
JJM		05/18/94	05/19/94	DI 9-88	A6359050		700 270

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
MOBILE SHOOTING CENTER INC
710 DYKES RD
MOBILE AL 36608

SHIP TO:
MOBILE SHOOTING CENTER INC
710 DYKES RD
MOBILE AL 36608

CUST NO:012252 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B2			E1	F1
TRIGGER GROUP		B3			E2	F2
BOLT ASSY.		B4		D1	E3	F3
BARREL ASSY.		B5		D2	E4	F4
REC. ASSY.			C1	D3	E5	F5
WOOD			C2			
METAL						

If any pressure, even from the side is exerted on the trigger and the safety is moved to the fire position the gun will fire

MAIN FAULT Mfgr 9-88 Pressure should not be applied anywhere on trigger when moving safety lever from safe to fire. Trigger pull and overtravel screws have been adjusted outside of the factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger at special price as gesture of good will.

PARTS

COMMENTS Trigger pull measured 2 3/4 to 3 as sent. Sear lift was .008

Stock is not of Remington mfg.

Trigger has been changed - bolt lock safety was not standard in 1988

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9