RECEIVING AND ESTIMATING REPORT

COMMENTS: Steel

ORDER R 92-06182

INITIAL: JJM | CUSTOMER ORDER NO.:

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/19/92	02/27/92	ED 10-83	B6502403		700 25-06 BDL

ACCESSORIES: W/STUDS L/REAR SIGHT

FROM:
MORRISON, NORMAN E
BOX 124
WILLIAMSTOWN VT 05679

SHIP TO:
MORRISON, NORMAN E
BOX 124
WILLIAMSTOWN VT 05679

CUST NO:058777 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST		3-20-92	UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Gun fired when moving Safety				E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Cannot duplicate complaint — trigger and safety assembly operates properly in every respect.

Trigger pull 4½ pounds; sear-lift .012"

PARTS

COMMENTS: Offer to return rifle as is, or to replace trigger assembly at normal cost as a gesture of good will if that will better motive satisfy Norman with the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/9