Set up file
Upgrade

RECEIVING AND ESTIMATING REPORT

COMMENTS: XC FS

ORDER: R 94-13438

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/18/94	04/19/94	RE 11-84	7639670		7 7MM-08

ACCESSORIES: W/STUDS SCOPE BASE L/REAR SIGHT

FROM:
PENN, RON
1111 ROUTE 6N
WATERFORD PA 16441

SHIP TO:
PENN, RON
1111 ROUTE 6N
WATERFORD PA 16441

CUST NO: 096164 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER NO.	WRITE	PROM. DATE	ESTIMATED	VIA
	059001	☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP ✓		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

When safety is pushed off, the safe fire. Trigger bounce when gun was

MAIN FAULT: Upon receipt could not duplicate known. However, examination revealed a thick heavy gummy substance inside the trigger housing and on the sear of the safety sear. Our tool and parts are after that ammo have been in use since mfg. 1984. Trigger bounce pin of gunsmith

PARTS
26345 trigger assembly
92458

COMMENTS: Trigger pull measured 3 1/2 to 3 3/4 lbs at sear. Sear lift was .014
Replace complete trigger assembly and clean action at 1/2 normal replacement cost, as gunsmith of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Barbara Bar
New #

JK

OFFICE COPY

R06925 REV. 1/94

to A/S
5/19/94