RECEIVING AND ESTIMATING REPORT

CUST NO:048491 C.O.D

COMMENTS

STEIKO

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
08/30/91	09/04/91	DH 9-87	B6894634	700 270 ADL	R 91-17327

ACCESSORIES W/STUDS
L/REAR SIGHT

FROM:
SCARBOROUGH, RONNIE J
3804 SHAWNCE DR
ANDERSON SC 29624
USA

SHIP TO:
SCARBOROUGH, RONNIE J
3804 SHAWNCE DR
ANDERSON SC
USA 29624

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ TARP	PROM. DATE	ESTIMATED	VIA
				9/20/91	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST Various malfunctions (see attached letter copy)

MAIN FAULT trigger assembly is reset from unknown cause — internal trigger parts are not moving properly — as received trigger assembly not functional.

PARTS

Replace trigger assembly at no-charge, as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RJS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 7/90