RECEIVING AND ESTIMATING REPORT

N C F. Supply

ORDER R 94-13082

INITIAL	CUSTOMER ORDER NO.
FPS	

CALL TAG ATTN: JACK KAST
W/SEE THRU SCOPE MNTS.

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/14/94	04/14/94	OI 7-76	A6331331		700 30-06 ADL

ACCESSORIES SLING STRAP W/STUDS W/SWIVELS

FROM:

SCREEN, TIM
2233 FIERO ST.
BATON ROUGE LA 70808

SHIP TO:

SCREEN, TIM
2233 FIERO ST.
BATON ROUGE LA 70808

CUST NO:095971 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	059015	☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

The weapon discharged when the safety lever was moved from the safe position to the fire position and safety lever must be moved to unload gun

MAIN FAULT Mfg. N/C Unable to duplicate customer concern, trigger functioned normally in every respect. Assy. was dry and clean. Replace trigger assy. at N/C as a gesture of good will and to restore customer confidence in rifle.

PARTS Trig. Assy. New Style

COMMENTS Change to new style safety per phone call 4/20/94
Sear lift measured .014 as rec'd
Trigger pull was 5 to 5 1/2 LBS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
HB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 1/94