RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: JIM STEKL

ORDER: R92-10617

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/16/92	04/27/92	PT 6-70	6347446		700 6MM REM ADL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
SKUTTLE MFG CO
ATTN: MARTY HANSELL
RT 10
MARIETTA OH 45750

SHIP TO:
SKUTTLE MFG CO
ATTN: MARTY HANSELL
RT 10
MARIETTA OH 45750

CUST NO:061294 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"The rifle has been [illegible] upon bolt closure"					
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: "~~[illegible]~~ firing pin will on metimes follow down when operating bolt briskly – Trigger assembly has been adjusted outside factory – Trigger pull measured at 2½ pounds (well below mfg. specs of 3½) – trigger extraction is not positive, due to this lightly [illegible]

Sear lift .010"

PARTS

COMMENTS: Offer to re-adjust present trigger assembly or, to replace trigger assembly at ½ normal cost. As a gesture of good-will, M it would better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9