RECEIVING AND ESTIMATING REPORT

COMMENTS: BBL HAS BEEN CUT OFF

ORDER: R 91-27118

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/19/91	12/30/91	RI 11-76	A6382712		700 22-250 BDL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
SOUTH WEST GUNS
107 S RICE
BOX 432
HAMILTON TX 76531
USA

SHIP TO:
SOUTH WEST GUNS
107 S RICE
BOX 432
HAMILTON TX
USA 76531

CUST NO:016102 C.O.DL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		1-14-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Gun goes off when bolt is closed, and when you					
BOLT ASSY.	take off safety.	B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Trigger assembly has been improperly adjusted outside factory Overtravel is greatly excessive — adjustment screw has no effect. Trigger movement somewhat sluggish & bolt release stiff — appears to be gummy lubrication residue.

Trigger pull 3.8 pounds; sear lift .007"

PARTS

COMMENTS: Install new trigger assembly and charge normal cost as estimated goes with.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV.