RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-01719

INITIAL	CUSTOMER ORDER NO.
FPS	K10899

STE

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/10/92	01/16/92	DE 9-84	B6613217		700 243 WIN ADL

ACCESSORIES W/STUDS SCOPE MNTS SCOPE BASE

FROM:
SPORTS WORLD
5800 S LEWIS SUITE 154
ATTN: TL DENTON
TULSA OK 74105

SHIP TO:
SPORTS WORLD
5800 S LEWIS SUITE 154
ATTN: TL DENTON
TULSA OK 74105

CUST NO:005259 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		1/30/92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"	B2				
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Cannot duplicate above complaint after numerous attempts. Trigger assembly and safety operate properly. Disassembly of safe det. reveal fair excessive amount of oil on bottom of lockwork and on and in trigger assembly.

Trigger pull 4 pounds; sear-lift .015"

PARTS

COMMENTS Offer to clean present trigger assy. if possible, if not possible, offer to install new trigger assembly at ½ normal cost, as a gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
RJC					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE