RECEIVING AND ESTIMATING REPORT

COMMENTS: W/OWNERS MANUAL

ORDER: R 92-07672

INITIAL	CUSTOMER ORDER NO.
JJM	K10998

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
03/06/92	03/18/92	OI 7-88	C6275546		700 270 ADL

ACCESSORIES: W/STUDS

FROM:
SPORTS WORLD
5800 S LEWIS SUITE 154
ATTN: TL DENTON
TULSA OK 74105

SHIP TO:
SPORTS WORLD
5800 S LEWIS SUITE 154
ATTN: TL DENTON
TULSA OK 74105

CUST NO:005259 WDLM L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"Gun will prematurely fire. Hammer will not always stand."

MAIN FAULT: Trigger assembly has rusted from unknown source. Internal parts not moving freely nor properly.

PARTS

COMMENTS: Replace trigger assembly at N/C, has gotten of customer good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BW					

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91