RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-08510

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
03/17/92	03/27/92	OF 7-85	B6723854		700 30-06 BDL/LH

ACCESSORIES: SLING STRAP W/STUDS W/SWIVELS SOFT CASE SCOPE BASE

FROM:
TOPHAM, DAVID
31 INDIAN TRAIL
HANSON MA 02341

SHIP TO:
TOPHAM, DAVID
31 INDIAN TRAIL
HANSON MA 02341

CUST NO:060099 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP					E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: "When I moved the safety lever to the fire position the gun discharged with the my finger being on the trigger."

No fault found — trigger assembly and safety operate properly — easily reject — cannot make fire mechanism after many attempts.

Trigger pull 3½ pounds; sear-lift .001"

PARTS

COMMENTS: Offer to return rifle as-is, or, if replace trigger assembly at $ 20.00 each is a certain of good-will & the will better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JJB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91