BARBER - Kinzer PPS GAL RE0005161

RECEIVING AND ESTIMATING REPORT

ORDER R 92-02556

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/14/92	01/21/92	DR 9-68	361473		700 30-06 ADL

ACCESSORIES W/STUDS

FROM:
TYLER, BRIAN
RD 1
BOX 172A
NEW MILFORD PA 18834

SHIP TO:
TYLER, BRIAN
RD 1
BOX 172A
NEW MILFORD PA 18834

CUST NO:056644 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		2-5	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1	trig. sticks, when you close bolt it fires			
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Trigger return spring not functioning properly — trigger pull has been improperly adjusted outside factory — return spring not active because trigger pull has been reduced to only 2 pounds — well below our minimum specification.

Sear left .010"

PARTS

COMMENTS Offer to re-adjust present trigger assembly to our specs, or we can install a new trigger assembly for ½ normal cost as a gesture of good-will if this is preferable

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTER
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

R06925 REV. 8