RECEIVING AND ESTIMATING REPORT

COMMENTS: W/BUSHNELL SPORTVIEW SCOPE Stelt

ORDER: R 92-02993

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/16/92	01/24/92	PE 6-84	B6597087		78 30-06

ACCESSORIES: W/STUDS SCOPE MNTS SCOPE BASE L/REAR SIGHT

FROM:
VAN HORN, RAY L
16 MILLER RD
TAWAS CITY MI 48763

SHIP TO:
VAN HORN, RAY L
16 MILLER RD.
TAWAS CITY MI 48763

CUST NO:056882 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		2-10-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Gun fired when taking Safety off	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Cannot duplicate complaint - find no fault with rifle or trigger assembly. Trigger assembly and safety operate properly in all respects

Trigger pull 5 1/4 pounds; rear sight .0125"

PARTS

COMMENTS: Offer to return rifle as-is, or offer to install trigger assembly at ½ shop cost as a gesture of good-will, if that would bolster customer confidence in the rifle & scope in CDR.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 8